

OCTOBER							
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
							1
SIP = shelter in place							Start of concrete saw-cutting from west of B-136 to west of B-134
	2	3	4	5	6	7	8
CPFN = carry projects forward as needed		East wing exhaust shutdown: 4:00 - 6:00 am Fume hood uncrating, for Phoenix valve installs; first floor east wing  FUME HOOD UNCRATING - 1st floor east side only		UNCRATE B-140, B-144, B-148	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  B-140: floor polishing	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE	
	9	10	11	12	13	14	15
		Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  B-140: Bring lab equipment from storage  B-144: Bring lab equipment from storage	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  B-140: Bring lab equipment from storage	Total ventilation shutdown in EAST wing; all three floors impacted. CONTINUES THROUGH MONDAY  Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  B-136 (OPT A): UNCRATE	Total ventilation shutdown in EAST wing; all three floors impacted. CONTINUES THROUGH MONDAY
	16	17	18	19	20	21	22
	Total ventilation shutdown in EAST wing; all three floors impacted. CONTINUES THROUGH MONDAY	Total ventilation shutdown in EAST wing; all three floors impacted. ENDS TODAY at 5:00 pm  Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  THIRD FLOOR WEST: preliminary work completion and ceiling close  B-136 (OPT A): Wax if uncrating accomplished Oct 14	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  B-136 (OPT A): Bring lab equipment from storage if uncrating accomplished Oct 14  B-136: (OPT B) UNCRATE if not already accomplished Oct 14  B-160: UNCRATE  B-148: Bring lab equipment from storage	Piping replacement/tie-in between west of B-136 to west of B-134; PEDESTRIAN REROUTE  B-136 (OPT B): wax floor if uncrating not accomplished until Oct 18  B-160 (OPT A): wax floor	B-136 (OPT B): Bring lab equipment from storage if floor waxing complete  B-136 (OPT C): wax floor if not already accomplished Oct 17 or 19  B-160 (OPT B): wax floor if not already accomplished Oct 19  B-156 Uncrate (DEPENDS ON SNORKEL INSTALL)  B-152: Uncrate and HEAVY EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from storage if floor waxing complete	B-136: Bring any remaining lab equipment from storage  B-160: Bring any remaining lab equipment from storage  B-156: wax floor if uncrated on Oct 20  B-152: wax floor if uncrated on Oct 20	
	23	24	25	26	27	28	29
		B-156: Bring lab equipment from storage  B-152: Bring lab equipment from storage					
	30	31					

--	--	--	--	--	--	--	--

NOVEMBER							
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
			1	2	3	4	5
SIP = shelter in place						MOVE-OUT: B-233 to B-207 (temp) - Suveen Mathaudhu	
	6	7	8	9	10	11	12
CPFN = carry projects forward as needed			MOVE-OUT: B-230 - miscellaneous stored items		MOVE-OUT: B-232 to B-207 - Hyle Park (includes B-232A,B)	VETERAN'S DAY HOLIDAY	
	13	14	15	16	17	18	19
		MOVE OUT - MSE 217, 205 TO STORAGE/AS NOTED MSE 201	FINISH MOVE-OUT: B-232 to B-207 Hyle Park (includes B-232A,B)	TSUTSUI AND FRANCO BACK INTO B-156 FROM STORAGE AND PIERCE 3301  FLOOR WAX - B-359??	MOVE-OUT: B-234 to B-359 - GS move back to original office (may be able to move up schedule if room available)		
	20	21	22	23	24	25	26
		MOVE OUT AND CRATE B-108 and B-134	MOVE OUT AND CRATE B-108 and B-134	MOVE OUR AND CRATE B-108 AND B-134	THANKSGIVING DAY HOLIDAY	THANKSGIVING HOLIDAY	
	27	28	29	30			
		MOVE-OUT: B-236 - WCGEC to B-255 and B-261	MOVE-OUT: B-236 - WCGEC to B-255 and B-261	MOVE-OUT: B-235 - CEE Analytical, Instructional Space			
DECEMBER							
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
					1	2	3
SIP = shelter in place					MOVE-OUT: B-235 - CEE Analytical, Instructional Space  MOVE-OUT: B-233 to B-207 (temp) - Suveen Mathaudhu HEAVY ITEMS to B-155, B-207  <del>MOVE-OUT: B-231 - B-213AA</del>	MOVE-OUT: B-235 - CEE Analytical, Instructional Space  MOVE-OUT: B-231 - B-213AA	FALL FINALS BEGIN
	4	5	6	7	8		10
CPFN = carry projects forward as needed		PHASE 3 HARD START  MSE 268, MSE 272, PIERCE 3301 TO 1/2 of B-238 WILL GROVER	MSE 268 and MSE 272 TO B-???: WILL GROVER	MSE 259B TO B-254: JUCHEN GUO (NOT IN ORIGINAL BURGESS ESTIMATE)	MSE 259B TO B-254: JUCHEN GUO	FINALS END	
	11	12	13	14	15	16	17
	18	19	20	21	22	23	24
	25	26	27	28	29	30	31
		HOLIDAY CLOSURE	HOLIDAY CLOSURE	HOLIDAY CLOSURE	HOLIDAY CLOSURE	HOLIDAY CLOSURE	

[illegible]

[illegible]