				OCTOBER			
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
CID — ab altau iu							Chart of compress con-
SIP = shelter in							Start of concrete saw-
place							cutting from west of B-13
	2	3	4	5	6	7	to west of B-134 8
CPFN = carry	-	East wing exhaust shutdown: 4:00 -	7	UNCRATE B-140, B-144, B-148	Piping replacement/tie-in between	Piping replacement/tie-in between	Ü
projects		6:00 am		011011111111111111111111111111111111111	west of B-136 to west of B-134;	west of B-136 to west of B-134;	
forward as		Fume hood uncrating, for Phoenix			PEDESTRIAN REROUTE	PEDESTRIAN REROUTE	
needed		valve installs; first floor east wing			FEDESTRIAN REROOTE	FEDESTRIAN REROOTE	
liceueu		valve ilistalis, ilist 11001 east willig			B-140: floor polishing		
		FUME HOOD UNCRATING - 1st floor			B-140. Hoor polishing		
		east side only					
	9	10	11	12	13	14	15
		Piping replacement/tie-in between	Piping replacement/tie-in between	Piping replacement/tie-in between	Piping replacement/tie-in between	Total ventilation shutdown in EAST	Total ventilation shutdow
		west of B-136 to west of B-134;	west of B-136 to west of B-134;	west of B-136 to west of B-134:	west of B-136 to west of B-134;	wing; all three floors impacted.	in EAST wing; all three
		PEDESTRIAN REROUTE	PEDESTRIAN REROUTE	PEDESTRIAN REROUTE	PEDESTRIAN REROUTE	CONTINUES THROUGH MONDAY	floors impacted.
							CONTINUES THROUGH
				B-140: Bring lab equipment from	B-140: Bring lab equipment from	Piping replacement/tie-in between	MONDAY
				storage	storage	west of B-136 to west of B-134;	
						PEDESTRIAN REROUTE	
				B-144: Bring lab equipment from			
				storage		B-136 (OPT A): UNCRATE	
	16	17	18	19	20	21	22
	Total ventilation shutdown	Total ventilation shutdown in EAST	Piping replacement/tie-in between	Piping replacement/tie-in between	B-136 (OPT B): Bring lab equipment	<b>B-136:</b> Bring any remaining lab	
	in EAST wing; all three	wing; all three floors impacted.	west of B-136 to west of B-134;	west of B-136 to west of B-134;	from storage if floor waxing complete	equipment from storage	
	floors impacted.	ENDS TODAY at 5:00 pm	PEDESTRIAN REROUTE	PEDESTRIAN REROUTE			
	CONTINUES THROUGH	·			B-136 (OPT C): wax floor if not	<b>B-160:</b> Bring any remaining lab	
	MONDAY	Piping replacement/tie-in between	B-136 (OPT A): Bring lab equipment	B-136 (OPT B): wax floor if	already accomplished Oct 17 or 19	equipment from storage	
		west of B-136 to west of B-134;	from storage if uncrating	uncrating not accomplished until			
		PEDESTRIAN REROUTE	accomplished Oct 14	Oct 18	B-160 (OPT B): wax floor if not	<b>B-156:</b> wax floor if uncrated on Oct	
			p		already accomplished Oct 19	20	
		B-136 (OPT A): Wax if uncrating	B-136: (OPT B) UNCRATE if not	B-160 (OPT A): wax floor	,,		
		accomplished Oct 14	already accomplished Oct 14		B-156 Uncrate (DEPENDS ON	<b>B-152:</b> wax floor if uncrated on Oct	
			an edd, decempioned eet 1		SNORKEL INSTALL)	20	
			İ	1			
			B-160: UNCRATE				
			B-160: UNCRATE		<b>B-152:</b> Uncrate and HEAVY		
					B-152: Uncrate and HEAVY FOLUPMENT MOVERS (Shift magnets)		
			<b>B-148:</b> Bring lab equipment from		EQUIPMENT MOVERS (Shift magnets)		
					EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL		
			<b>B-148:</b> Bring lab equipment from		EQUIPMENT MOVERS (Shift magnets)		
			<b>B-148:</b> Bring lab equipment from		EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)		
			<b>B-148:</b> Bring lab equipment from		EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from		
			<b>B-148:</b> Bring lab equipment from		EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)		
	23	24	<b>B-148:</b> Bring lab equipment from	26	EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from	28	29
	23	24 B-156: Bring lab equipment from	<b>B-148:</b> Bring lab equipment from storage	26	EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from storage if floor waxing complete	28	29
	23		<b>B-148:</b> Bring lab equipment from storage	26	EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from storage if floor waxing complete	28	29
	23	B-156: Bring lab equipment from	<b>B-148:</b> Bring lab equipment from storage	26	EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from storage if floor waxing complete	28	29
	23	B-156: Bring lab equipment from	<b>B-148:</b> Bring lab equipment from storage	26	EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from storage if floor waxing complete	28	29
	23	<b>B-156:</b> Bring lab equipment from storage	<b>B-148:</b> Bring lab equipment from storage	26	EQUIPMENT MOVERS (Shift magnets) (DEPENDS ON HOOD/SNORKEL INSTALL)  B-160: Bring lab equipment from storage if floor waxing complete	28	29

		T	Τ	
		1	1	

				NOVEMBER			
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
			1	2	3	4	5
SIP = shelter in			MOVE-OUT: B-230 - miscellaneous	MOVE-OUT: B-231 - B-207	MOVE-OUT: B-231 - B-207	MOVE-OUT: B-233 to B-207 (temp)	
place			stored items	miscellaneous faculty	miscellaneous faculty	Suveen Mathaudhu	
		7	8	9	10	11	12
CPFN = carry	6	/ MOVE-OUT: B-233 to B-207 (temp)	<u> </u>	MOVE-OUT: B-232 to B-207 - Hyle	10	11	12
projects		Suveen Mathaudhu HEAVY ITEMS	-	Park (inlcudes B-232A,B)			
forward as		Suveen Mathaduna HEAVT HEIMS	raik (iiiicudes B-232A,B)	Fair (inicudes B-232A,B)			
needed							
Heeded	13	14	15	16	17	18	19
		MOVE-OUT: B-234 to B-359 - GS					
		move back to original office (may					
		be able to move up schedule if					
		room available)					
	20	21	22	23	24	25	26
			MOVE OUT AND CRATE B-108 and B	MOVE OUR AND CRATE B-108 AND			
		134	134	B-134			
				PHASE 3 HARD START			
	27	28	29	30			
			MOVE-OUT: B-236 - WCGEC to B-	MOVE-OUT: B-235 - CEE Analytical,			
		255 and B-261	255 and B-261	Instructional Space			
				DECEMBER			
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
our I II I					1	2	3
SIP = shelter in					MOVE-OUT: B-235 - CEE Analytical,		FALL FINALS BEGIN
place	4	5	6	7	Instructional Space 8	9	10
CPFN = carry	4		MSE 268 and MSE 272 TO B-???:	,	MSE 259B TO B-254: JUCHEN GUO	9	10
projects			WILL GROVER	WISE 259B TO B-254. JOCHEN GOO	WISE 255B TO B-254. JOCHEN GOO		
forward as		WILL GROVEN	WILL GROVER			FINALS END	
needed							
	11	12	13	14	15	16	17
	18	19	20	21	22	23	24
	35	26	27	30	30	20	24
	25	26	27	28	29	30	31
				JANUARY			
	SUNDAY	MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY
							1
SIP = shelter in							
place							
	2	3	4	5	6	7	8
SIP = shelter in							
place	0	10	11	12	12	1.0	15
	9	10	11	12	13	14	15

Projects   FEBRUARY   FRIDAY   SA   SA   SA   SA   SA   SA   SA	22 29 ATURDAY 1 8
16	29 ATURDAY 1  8
SUNDAY   MONDAY   TUESDAY   WEDNESDAY   THURSDAY   FRIDAY   SANDACE	ATURDAY 1 8
30   31	ATURDAY 1 8
SUNDAY   MONDAY   TUESDAY   WEDNESDAY   THURSDAY   FRIDAY   SAN SIP = shelter in place   2   3   4   5   6   7	1 8 15
SUNDAY   MONDAY   TUESDAY   WEDNESDAY   THURSDAY   FRIDAY   SY	1 8 15
SIP = shelter in place  2 3 4 5 6 7  CPFN = carry projects forward as needed  9 10 11 12 13 14  16 17 18 19 20 21  23 24 25 26 27 28	1 8 15
Diace   2   3   4   5   6   7	15
CPFN = carry projects forward as needed  9 10 11 12 13 14  16 17 18 19 20 21  23 24 25 26 27 28  30 31	15
projects forward as needed 9 10 11 12 13 14 14 15 16 17 18 19 20 21 15 16 17 28 15 16 17 18 19 20 21 15 16 17 18 19 20 21 15 16 17 18 19 20 19 20 21 19 20 21 19 20 21 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 25 26 27 28 28 28 26 27 28 28 28 28 28 28 28 28 28 28 28 28 28	
9 10 11 12 13 14 14 15 16 17 18 19 20 21 21 23 24 25 26 27 28 30 31	
23     24     25     26     27     28       30     31	22
30 31 SI	
	29
MARCH  MA	